

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

NASA Industrial Plant, Cryogenic Test Lab/ Hazardous Storage
(NASA Industrial Plant, Storage and Tool Crib)
(NASA Industrial Plant, Building No. 125)
12214 Lakewood Boulevard
Downey
Los Angeles County
California

HAER No. CA-310-L

Positive Image Photographic Services, Tavo Olmos, Photographer, December 2002.

CA-310-L-01 EXTERIOR BLDG. 125 SOUTHWEST CORNER VIEW, FACING
NORTHEAST.

CA-310-L-02 EXTERIOR BLDG. 125 SOUTHEAST CORNER VIEW, FACING
NORTHWEST.

CA-310-L-03 EXTERIOR BLDG. 125 NORTH SIDE DETAIL VIEW, FACING
SOUTHEAST.

CA-310-L-04 EXTERIOR BLDG. 125 NORTHEAST CORNER VIEW, FACING
SOUTHWEST.

CA-310-L-05 INTERIOR BLDG. 125 EAST ROOM DETAIL VIEW, FACING
NORTHWEST.

CA-310-L-06 INTERIOR BLDG. 125 CENTER ROOM DETAIL VIEW, FACING
SOUTHEAST.

See contextual photographs in HAER report No. CA-310 for views of
Building 125.